# STATE OF FLORIDA **DEPARTMENT OF HEALTH COUNTY HEALTH DEPARTMENT PUBLIC SCHOOL INSPECTION REPORT**



1 of 3

**Facility Information** 

Permit Number: 13-51-08303 Name of Facility: Hibiscus El. Address: 18701 NW 1 Avenue

City, Zip: Miami 33169 Type: Public Schools

Owner: MDCPS Person In Charge: MDCPS- Sherry Alouidor

PIC Email: salouidor@dadeschools.net

**RESULT: Satisfactory** 

Correct By: Next Inspection Re-Inspection Date: None

Inspection Information

Purpose: Routine Begin Time: 10:10 AM Inspection Date: 6/3/2024 End Time: 11:30 AM

Phone: (786) 275-0400

**Additional Information** 

FEMALES ..... 182 CENSUS ..... 369 MALES .... 187

This form serves as a "Notice of Non-Compliance" pursuant to section 120.695, Florida Statutes. Items marked below violate one or more of the requirements of Rule 6A-2.0010, of the Florida Administrative Code, Chapter 5, section 5 of the State Requirements for Educational Facilities 2014 (SREF); and sections 453 and 468 of the Florida Building Code 6th Edition (2017). Violations must be corrected within the time period indicated above. Continued operation of this facility without making these corrections is a violation. Failure to correct violations in the time frame specified may result in enforcement action being initiated by the Department of Health.

### **Violation Markings**

SCHOOL SANITATION

IN 1. School Site

IN 2. Playground, Equip & Athletic Fields\*

NA 3. Athletic & Playground Equipment BUILDING CONST/MAINT.

OUT 4. Construction

OUT 5. Maintenance & Repair

N 6. Lighting Standards

N 7. Heating, Ventilation, A/C Standards
N 8. Natural Ventilation

9. Mechanical Ventilation SANITARY FACILITIES

IN 10. Provided/Accessible/Separation

IN 11. Group Toilet Rooms

IN 12. Toilet Facilities

IN 13. Handwashing Facilities

IN 14. Soap Dispensers

NA 15. Shower Facilities

NA 16. Showers Water Temperatures WATER SUPPLY

IN 17. Approved Source IN 18. Drinking Fountains

LIQUID WASTE & WASTE WATER

IN 19. Sewage Disposal IN 20. Solid Waste

PEST CONTROL

IN 21. Pest Control SAFETY

IN 22. First Aid Kit

DIAPER CHANGING STATION

NA 23. Sanitizers

NA 24. Changing Station & Mats

NA 25. Hand Sink NA 26. Garbage Can

**ANIMAL HEALTH & SAFETY** 

NA 27. Animal Maintenance/Aggressive DORM/RESIDENTIAL FACILITIES

NA 28. Maintenance/Complaint

NA 29. Other

Marking Key: IN = the act or item was observed to meet standards; OUT = the act or item was observed not to meet standards; NO = the act or item was not observed to be occurring at the time of inspection; NA = the act or item is not performed by the facility or not part of the operation

Violation Key: \* = 2. Playground, Equipment & Athletic Fields

**Inspector Signature:** 

**Client Signature:** 

13-51-08303 Hibiscus El. Form Number: DH 4030 12/16A

# STATE OF FLORIDA DEPARTMENT OF HEALTH COUNTY HEALTH DEPARTMENT PUBLIC SCHOOL INSPECTION REPORT



2 of 3

### **General Comments**

Inspection satisfactory

Email Address(es): Salouidor@dadeschools.net;

MWertz@dadeschools.net; IPalacio@dadeschools.net; wcabrera@dadeschools.net; Edvelez@dadeschools.net;

## **Violations Comments**

Violation #4. Construction

At the time of inspection observed outside media center tree branch growing in between construction , causing damage to the walls . Remove tree from wall area and conduct wall repair .

CODE REFERENCE: 4. Construction, Remodeling and Renovation. 5(1)(f) SREF. Remodeling, renovation, and correction of deficiencies of existing educational, auxiliary, and ancillary facilities shall comply with the new construction requirements found in the Florida Building Code and the Florida Fire Prevention Code.

Violation #5. Maintenance & Repair

At the time of inspection observed in restroom 129 ladies' handwashing water running nonstop . Repair handwash sink .

At the time of inspection observed in classroom 023 one flickering light (57 Ft) . Replace light.

At the time of inspection observed in classroom 007 one damage ceiling tile. Replace ceiling tile.

At the time of inspection observed at classroom 006, 13 lights out (50 Ft). Replace lights.

At the time of inspection observed at classroom 005 , 5 lights out  $\,$  (55 Ft  $)\,$  . Replace lights .

At the time of inspection observed at classroom 004, 17 lights out (51 Ft) . Replace lights.

At the time of inspection observed at classroom 009, 3 lights out (57 Ft) . Replace lights .

At the time of inspection observed at classroom 010, 10 lights out  $\,$  (54 Ft  $)\,$  . Replace lights.

At the time of inspection observed at classroom 006, 13 lights out (52 Ft) . Replace lights.

At the time of inspection observed at classroom 012, 6 lights out (52 Ft). Replace lights.

At the time of inspection observed at classroom 110, 1 light out (52 Ft). Replace lights.

At the time of inspection observed at media room 12 ceiling lights out (55 Ft). Replace lights.

At the time of inspection observed at building 120 corridor, two lights out (54 ft). Replace lights.

CODE REFERENCE: 5. Maintenance and Repair. 5(1)(e)8.h SREF. Light fixtures and window surfaces, both inside and outside, shall be kept clean, serviceable, and in good repair at all times. 5(1)(e)8.i. Custodial areas shall be kept clean, safe, and orderly at all times. Custodial equipment shall be in good repair at all times. 5(1)(e)8.j SREF. Building components & finishes shall be kept clean & in good repair.

Inspector Signature:

Client Signature:

Form Number: DH 4030 12/16A 13-51-08303 Hibiscus El.

# STATE OF FLORIDA DEPARTMENT OF HEALTH COUNTY HEALTH DEPARTMENT PUBLIC SCHOOL INSPECTION REPORT



3 of 3

Inspection Conducted By: Alexander Olaya (67699) Inspector Contact Number: Work: (305) 623-3500 ex.

Print Client Name: Sherry Alouidor

Date: 6/3/2024

Inspector Signature:

Client Signature:

Form Number: DH 4030 12/16A 13-51-08303 Hibiscus El.